

# Inspection Photos

API: 017-07717

Operator: **VECTA OIL & GAS LTD**

Inspection Date: 5/19/2025

County: CHEYENNE



## Inspection Photos



**Photo 1.** Facing southeast toward the access road which has revegetated.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 2.** Facing southeast at the location. The cattleguard has not been removed from the location. The perimeter fence was removed but not the cattleguard.



## Inspection Photos



**Photo 3.** Center of the location facing north. Perennial vegetation is progressing throughout the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 4.** Center of the location facing west. Perennial vegetation is progressing throughout the location.



## Inspection Photos



**Photo 5.** Center of the location facing south. Perennial vegetation is progressing throughout the location.



## Inspection Photos



**Photo 6.** Center of the location facing east. Perennial vegetation is progressing throughout the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources