

Inspection Photos

API: 017-06611

Operator: **MULL DRILLING COMPANY INC**

Inspection Date: 5/19/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at beginning of the access road. The cattleguard has not been removed and two track road remains.



Inspection Photos



Photo 2. Facing northwest along the access road which remains elevated and crowned. The road must be regraded and contoured.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing northwest toward the associated tank battery location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos




Photo 4. Facing southeast at the tank battery location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing northwest toward the wellsite.

