

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2025

Submitted Date:

05/15/2025

Document Number:

693808655

FIELD INSPECTION FORMLoc ID 316854 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10841

Name of Operator: AMERICAN HELIUM LLC

Address: 23501 CINCO RANCH BLVD, B244

City: KATY State: TX Zip: 77494

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Joyner, Ryan	970.385.6289	rjoyner@blm.gov	Tres Rios
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256999	WELL	PA	05/20/2005	GW	113-06076	FOSSIL FEDERAL 9	PA
277752	WELL	SI	04/01/2023	GW	113-06181	FOSSIL FEDERAL 9R	SI

General Comment:

ECMC staff performed a routine field inspection on 5/12/2025.
 Issues were found requiring corrective action. See inspection text and photos for details.
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign on meter housing		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No labels on condensate tank		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/16/2025

Emergency Contact Number:

Comment:	435-631-2239	
Corrective Action:		Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:	Dehaydrator		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	<100 BBLs	PBV STEEL		38.078916,-108.704646	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		38.078455,-108.704745	
Comment:	Tanks are rusted , pitted, or peeling paint, or show evidence of inadequate repair.					
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.					Date: 06/16/2025

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 256999

Type: WELL

API Number: 113-06076

Status: PA

Insp. Status: PA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: Well converted to water well.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277752

Type: WELL

API Number: 113-06181

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment: Tubing valve locked out by BLM.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/07/2025

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Date Run: 5/22/2025 Doc [#693808655]

Page 5 of 6

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404207211	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052419
693808656	Inspection photos 5/12/2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052413