

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2025

Submitted Date:

05/15/2025

Document Number:

707603908

FIELD INSPECTION FORM

Loc ID 434745	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 8 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 8960 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY Address: 555 17TH STREET SUITE 3700 City: DENVER State: CO Zip: 80202				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections
Steinke, Ivan		isteinke@civiresources.com	Regulatory Manager; DJ Basin

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434745	LOCATION	AC			-	State North Platte O-26 Pad	AO

General Comment:

This is a LOCATION inspection.

Well(s): 13: Producing | PR.

Battery: Active.

Centralized Battery serves 12 Location IDs

(432636, 434745, 429060, 310744, 433511, 454278, 432395, 441915, 434121, 332135, 445363, 470863).

(Well(s): 85: Producing | PR; 13: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID

(481579).

****This is a FOLLOW_UP INSPECTION.**

FWP to FIELD INSPECTION REPORT DOC #707603671 dated 01/29/2025.

Corrective Action(s) from prior inspection report remain UNADDRESSED and applicable.

Corrective Action(s) from prior inspection report date: 03/21/2025. FAILED to MITIGATE.

NEW CORRECTIVE ACTION DATE: 05/29/2025. (2-Weeks).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Location signage.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unnecessary equipment at Location site. See North side of Location site. Unnecessary equipment includes: Frac tank w/ spill pad. Refer to Rule 606 for guidance.		
Corrective Action:	*Remove unnecessary equipment from Location site. Comply with Rule 606. Prior Corrective Action date: 03/21/2025. NEW Corrective Action date: 05/29/2025. See photo(s) #1, 2, 3, 6, 7. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: 05/29/2025

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	434745	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 05/09/2025 at approximately 13:11 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: State North Platte/O-26 Pad Location ID: 434745 Well Name(s) & API: Reference: **FIR document #707603615, dated 01/29/2025. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 13: Producing PR. Battery: Active.</p> <p>**CORRECTIVE ACTION(s) COMMENT: During this inspection the following possible compliance issue(s) were observed: 1.) Unnecessary equipment at Location site. See North side of Location site. Unnecessary equipment includes: Frac tank w/ spill pad. Refer to Rule 606 for guidance. *Remove unnecessary equipment from Location site. Comply with Rule 606. Prior Corrective Action date: 03/21/2025. NEW Corrective Action date: 05/29/2025. See photo(s) #1, 2, 3, 6, 7. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/15/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404206936	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052007

707603909	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051988
-----------	---------------	---

