

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2025

Submitted Date:

05/14/2025

Document Number:

716300978

FIELD INSPECTION FORM

Loc ID 307272 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217336	WELL	PR	07/13/1998	CBM	071-06112	BURRO CANYON 34-28	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	PHOTO 4: PRODUCED WATER TANK BATTERY. NFPA, CAPACITY AND CONTENTS NOT LABELED ON TANK.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 05/19/2025
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 7: UNUSED EQUIPEMENT (UNUSED RISERS NOT MARKED OR LABELED INSIDE UNUSED SHED).		
Corrective Action:	MARK OR REMOVE UNUSED AND OR UNNESSESARY RISERS PER RULE 606. CA DATE 6/14/2025.		Date: 06/14/2025
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 6: UNUSED EQUIPMENT (SHED DOES NOT APPEAR TO BE IN USE OR USEFUL TO THE OPERATION OF THIS FACILITY, SHED IS DETERIORATING AND TRASH AND DEBREE FROM SHED IS ON AND AROUND LOCATION).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606.		Date: 06/14/2025
Type	TRASH		
Comment:	PHOTO 8 - 12: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED.		
Corrective Action:	INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606.		Date: 05/19/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	PHOTO 5: BIRD PROTECTORES MISSING OR NOT INSTALLED ON TWO PIPES IN TOP OF TANK.		
Corrective Action:	INSTALL BIRD PROTECTORS.	Date:	05/19/2025
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 217336 Type: WELL API Number: 071-06112 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404206945	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052014
716300979	INSP. POTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051991