

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2025

Submitted Date:

05/22/2025

Document Number:

717100203**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Rollins, Grace 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|--------------------------|--|
| Mickelson, Erik | | Erik_Mickelson@oxy.com | Oxy Environmental |
| , | | ECMCInspections@Oxy.com | All Inspections |
| Kiel, Macy | 970-515-1110 | Macy_Kiel@oxy.com | Staff Environmental Engineer |
| Brown, Kari | | kari.oakman@state.co.us | |
| Graber, Nikki | | nikki.graber@state.co.us | |

General Comment:**ECMC Field Inspection Report Summary**

This is an environmental inspection to determine progress on Spill ID 490165 and Remediation Project # 36214. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 490165

Spill Name: Paragon Farms 42-25

Remediation Project #: 36214

Facility ID: 487123

Reported Date of Discovery: 05/07/2025

Date of Inspection: 05/14/2025

Spill is located within or adjacent to:

-Crop land (immediately adjacent, all directions)

Current site status:

-Two excavations remain open on location at the former produced water vessel and separator.

-No environmental impacts were visible in situ and no groundwater was observed in the open excavations.

-Orange construction fencing has been installed at both excavations but does not encompass the entire perimeter of the excavation in the area of the former separator.

-Three unmarked soil stockpiles are visible on location; no liners were visible.

-Signage with emergency contact number is visible.

[See attached corrective actions.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---|--|------------------|
| Type | OTHER | | |
| Comment: | Orange construction fencing has been installed at both excavations but does not encompass the entire perimeter of the excavation in the area of the former separator. | | |
| Corrective Action: | Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v. | | Date: 06/05/2025 |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation Project # 36214 was created for decommissioning of the Paragon Farms 42-25 facility. Two excavations remain open on location at the former produced water vessel and separator. No environmental impacts were visible in situ and no groundwater was observed in the open excavations. Quarterly reporting is required under Remediation Project # 36214.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

| Type | Management | Condition | GPS (Lat) | (Long) |
|-------------------|--|-----------|-----------|-------------|
| | Piles | | | |
| Comment | Three unmarked soil stockpiles are visible on location; no liners were visible. | | | |
| Corrective Action | Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil. | | | Date: _____ |

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 717100204 | ECMC Photo Log - Paragon Farms 42-25 - 5.14.2025 | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7061172 |