

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2025

Submitted Date:

05/22/2025

Document Number:

719000107

FIELD INSPECTION FORMLoc ID 306779 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264621	WELL	PR	11/21/2002	CBM	067-08746	ANDERSON 1 (1R)	PR

General Comment:

Inspection Report Summary
 On 5/21/25 I Inspector Charles Garcia
 conducted an on-site inspection.
 Location: ANDERSON #1 (1r)
 Operator:HILCORP ENERGY COMPANY
 API#: 067-08746
 County: LaPlata

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	LOCATION SGIN AT ENTRANCE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	505-324-5170 911 EMERGENCY	Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	OIL STAIN ON SIDE OF GAS ENGINE FORM PRIME MOVER MUFFLER SYSTEM		
Corrective Action:	CLEAN UP STAINED SOILS AND DISPOSE IN APPROVED MANNER RULE 1002.f TO PREVENT SITE DEGRADATION	Date:	06/22/2025

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	4FT HOG WIRE		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	CATTLE PANLES SOUND WALLS		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	CHEMICAL INJECTION CONTAINER WITH SPILL PREVENTION LABEL STARTING TO PEEL OFF		

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	METERHOUSE LAST CALIABRATION 2/25/25		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	LUBE CONTAINER FOR PRIME MOVER NO SPILL PREVENTION		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	OIL STAIN ON SIDE OF PRIME MOVER FROM ENGINE MUFFLER LEAK SEE LOCATION PICTURES		
Corrective Action:	MAINTAIN ENGINE MUFFLER SYSYEM SO ITS NOT IMPACTING SOIL	Date:	06/22/2025
Type: Deadman # & Marked	# 6		
Comment:	3 MARKERS LAYING ON GROUND		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	PBV STEEL		37.025110,-107.317630
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	264621	Type:	WELL	API Number:	067-08746	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	06/11/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000112	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7062065