

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2025

Submitted Date:

05/21/2025

Document Number:

696307636

**FIELD INSPECTION FORM**Loc ID 433993 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment                         |
|--------------|-------|--------------------------|---------------------------------|
| ,            |       | Regulatory@verdadoil.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 433991      | WELL | TA     | 10/25/2021  | OW         | 123-37895 | State 4-36-9-61 | TA          |
| 433992      | WELL | PR     | 10/01/2024  | OW         | 123-37896 | State 3-36-9-61 | TA          |
| 433994      | WELL | PR     | 09/01/2024  | OW         | 123-37897 | State 2-36-9-61 | TA          |

**General Comment:**

This is a Well PAD Field Compliance Audit

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | STORAGE OF SUPL  |       |            |
| Comment:           | Wells appear to be Pugged and Abandoned - 3 Months have past on 4-36-9-61 and 3-36-9-61 to Remove all Surface Equipment<br>3 Months is approaching for 2-36-9-61 |       |            |
| Corrective Action: | Comply with Rule 1004  | Date: | 06/06/2025 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | LOCATION    |       |  |
| Comment:           | Barbed Wire |       |  |
| Corrective Action: |             | Date: |  |

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>             |     |       | corrective date |
| Type: Emission Control Device | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Vertical Heater Treater | # 3 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Vertical Separator      | # 3 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |

**Venting:**

|        |  |  |
|--------|--|--|
| Yes/No |  |  |
|--------|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

Inspected Facilities

Facility ID: 433991

Type: WELL

API Number: 123-37895

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Appears to have been Plugged and Abandoned pre Form 6S 404034533 dated 01.06.2025 (In Process) with a Surface Plug date of 12.04.2024 and a Cut and Cap Date of 12.12.2024

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433992

Type: WELL

API Number: 123-37896

Status: PR

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Appears to have been Plugged and Abandoned pre Form 6S 404034431 dated 01.06.2025 (In Process) with a Surface Plug date of 12.04.2024 and a Cut and Cap Date of 12.12.2024

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433994

Type: WELL

API Number: 123-37897

Status: PR

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Appears to have been Plugged and Abandoned pre Form 6S 404121449 dated 03.10.2025 (In Process) with a Surface Plug date of 02.07.2025 and a Cut and Cap Date of 02.26.2025

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment  | User   | Date       |
|--|--------|------------|
| <div>Routine Field Compliance Audit.<br/>Wells appear to be Pugged and Abandoned - 3 Months have past on 4-36-9-61 and 3-36-9-61 to Remove all Surface Equipment<br/>3 Months is approaching for 2-36-9-61 - Comply with Rule 1004</div> | petrie | 05/21/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404213389    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7060173">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7060173</a> |
| 696307637    | Photos               | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7060168">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7060168</a> |