


**Inspection Photos**  
**Location: State 16 SWSE 3054**  
**Location ID: 483008**  
**API # 05-071-09922**



**Photo 1 –Well placard**



**Photo 2 – Wellhead**

**Inspection Photos**  
**Location: State 16 SWSE 3054**  
**Location ID: 483008**  
**API # 05-071-09922**



**Photo 3 – Well placard has not secured to frame**

**Photo 4 – Sandbag/debris on location**