

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2025

Submitted Date:

05/28/2025

Document Number:

710500516**FIELD INSPECTION FORM**Loc ID 483008 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10763Name of Operator: BNL (ENTERPRISE) INCAddress: 6494 S QUEBEC STCity: ENGLEWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kondrat, Peter	970-759-5370	pkondrat@bluestarhelium.com	All Inspections
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483503	WELL	SI	06/01/2024		071-09922	State 16 SWSE 3054	EI

General Comment:[This is an Environmental Inspection for the State 16 SWSE 3054 well location located in Las Animas County, Colorado](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Well placard at entrance to location had become dislodged from metal frame. Comply with Rule 605.g.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	DEBRIS		
Comment:	Sandbag left on location Comply with Rule 606		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	483503	Type:	WELL	API Number:	071-09922	Status:	SI	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spill/Remediation:**

Comment: This is an Environmental Inspection for Remediation Project # 36406. At the time of inspection, there were no visual signs of impacted materials observed. Operator shall continue quarterly reporting until all COA assigned in Form 27 Document # 403844978 are addressed.

At the time of inspection, quarterly report is 222 days late

Corrective Action: Operator shall continue quarterly reporting in accordance with Rule 913.e

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
Silt fence identified in Reclamation Inspection, Document # 713601881 has been removed.	sanchezcc	05/28/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500517	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7068590