

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HICKS PA 24-6 Pad

Location ID: 437097



Photo # 4387 From entrance to location



Photo # 4388 From entrance to location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HICKS PA 24-6 Pad

Location ID: 437097




Photo # 4389 Location



Photo # 4390 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HICKS PA 24-6 Pad

Location ID: 437097



Photo # 4391 Location



Photo # 4392 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HICKS PA 24-6 Pad

Location ID: 437097



Photo # 4393 Location



Photo # 4394 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HICKS PA 24-6 Pad

Location ID: 437097



Photo # 4395 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 4396 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HICKS PA 24-6 Pad

Location ID: 437097



Photo # 4397 Stored shipping container, camper, trailer, boat & truck bed



Photo # 4398 Stored shipping container, camper, boat & truck bed

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HICKS PA 24-6 Pad

Location ID: 437097



Photo # 4399 Stored shipping container & trailer



Photo # 4400 Stored shipping container & trailer