

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N. PARACHUTE WF I25 596 Pad

Location #: 335590



Photo # 6379 From entrance to location



Photo # 6380 From entrance to location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N. PARACHUTE WF I25 596 Pad

Location #: 335590



Photo # 6381 Location



Photo # 6382 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N. PARACHUTE WF I25 596 Pad

Location #: 335590



Photo # 6383 Location



Photo # 6384 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N. PARACHUTE WF I25 596 Pad

Location #: 335590



Photo # 6385 Location



Photo # 6386 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N. PARACHUTE WF I25 596 Pad

Location #: 335590



Photo # 6387 Location



Photo # 6388 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N. PARACHUTE WF I25 596 Pad

Location #: 335590



Photo # 6389 Location



Photo # 6390 Unused flowline does not comply with CECMC rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC N. PARACHUTE WF I25 596 Pad

Location #: 335590



Photo # 6391 Unused flowline does not comply with CECMC rules