

WGS84 $\pm 23\text{ft}$ 40.09164, -105.01878 $\Delta^m_{\pm 6\text{m}}$ 1519 $\triangle^{\circ, T}_{\pm 10}$ N6



ECMC
Environmental
Field Inspection



Anderson Trust #1
© 21-May-25 09:23:26 AM
ECMC Environmental Inspection

The access road to the wellhead was impassable by vehicle due to debris (logs/fence posts). The access road was overgrown.



ECMC
Environmental
Field Inspection



Anderson Trust #1
© 21-May-25 09:26:11 AM
ECMC Environmental Inspection

Signage with emergency contact number is visible.



Pooled fluid is visible around the wellhead. Inspects were visible swarming the pooled fluid.

WGS84 $\pm 10\text{ft}$ 40.09161, -105.01801 $\Delta^m_{\pm 3m}$ 1522 $\triangle^{\circ,T}_{\pm 11}$ NW291



ECMC
Environmental
Field Inspection



Anderson Trust #1
© 21-May-25 09:30:56 AM
ECMC Environmental Inspection

Signage with emergency contact number is visible. Production tank labels are becoming illegible.



Anderson Trust #1
⌚ 21-May-25 09:31:46 AM
ECMC Environmental Inspection
Weeds were visible on the production tank berm.

WGS84 $\pm 13\text{ft}$ 40.09156, -105.01856 $\wedge^m_{\pm 3\text{m}}$ 1520 $\triangle^{\circ, T}_{\pm 11}$ NE48



ECMC
Environmental
Field Inspection



Anderson Trust #1
© 21-May-25 09:33:41 AM
ECMC Environmental Inspection

Vehicular rutting was visible on location.