



State 14
© 21-May-25 09:57:33 AM
ECMC Environmental Inspection

Signage with emergency contact number is visible at the wellhead.

WGS84 40.09689, -104.94456 Δ m 1525 \angle °, T SW220
±13ft ±3m ±11



ECMC
Environmental
Field Inspection



State 14
© 21-May-25 10:00:20 AM
ECMC Environmental Inspection

WGS84 40.09689, -104.94461 $\Delta^m_{\pm 4m}$ 1521 $\Delta^{\circ}_{\pm 14}$ NE55



Stained soil was visible around the wellhead. A strong petroleum hydrocarbon odor was observed when the stained soil was disturbed.



State 14
© 21-May-25 10:01:08 AM
ECMC Environmental Inspection

Stained soil was visible around the wellhead. A strong petroleum hydrocarbon odor was observed when the stained soil was disturbed.



WGS84 40.09688, -104.94458 Δ $\pm 5m$ 1524 Δ ± 12 °T E78

ECMC
Environmental
Field Inspection



State 14
© 21-May-25 10:01:28 AM
ECMC Environmental Inspection

Free product was visible on water beneath the wellhead.



State 14
© 21-May-25 10:02:02 AM
ECMC Environmental Inspection

Trash was visible adjacent to the wellhead.

WGS84 $\pm 11\text{ft}$ 40.09685, -104.94442 $\wedge^m_{\pm 4\text{m}}$ 1520 $\triangle^{\circ, T}_{\pm 11}$ NW292



ECMC
Environmental
Field Inspection



State 14
© 21-May-25 10:03:33 AM
ECMC Environmental Inspection

An unmarked soil stockpile was observed on location with no stormwater BMPs; no liner was visible.

WGS84 40.09674, -104.94450 Δ ^m_{±4m} 1521 \triangle [°]_{±11} W257



ECMC
Environmental
Field Inspection



State 14
© 21-May-25 10:03:48 AM
ECMC Environmental Inspection

Orange construction fencing is visible attached to fence posts at the edge of the location (trash).



Approximate spill location. Excavation has been backfilled. Vegetation growth appears limited.



Approximate spill location. Excavation has been backfilled. Vegetation growth appears limited.