

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2025

Submitted Date:

06/10/2025

Document Number:

717300367

FIELD INSPECTION FORMLoc ID 329533 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249682	WELL	TA	12/01/2021	GW	123-17485	HSR-WADDELL 13-24A	PA
445757	LOCATION	AC			-	HSR-WADDELL-63N67W Tank	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 249682 Type: WELL API Number: 123-17485 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445757 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404223885 received on 06/02/2025: While conducting wellhead plugging and abandonment and flowline removal activities at the Waddell 13-24A wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown.	maclarej	06/10/2025
(2) wells are Plugged and abandoned (HSR-Waddell 12-23, 12 24A). ECMC form 42 notice of start of plugging operations doc #404073469 received 01/29/2025. Flowline cut ends (below grade, valved & capped) observed inside fenced PA well area; flowline risers are isolated, valved at HHS (OOSLAT). Flowline AIP work is in progress. Facility decommissioning work has not been started. No Oxy personnel on location during inspection.	maclarej	06/10/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300368	Signage and tank battery	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7089621
717300369	HHS Equipment; FL manifold isolated/ OOSLAT	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7089622
717300370	PA well; FL AIP in progress	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7089623