

Final Reclamation and Stormwater Inspection

Date: 06/10/2025

Operator: RAMPART ENERGY COMPANY - 5685

Location ID: 387259

Inspection Document #: 718700462

Logan County, CO




COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Schrader J8
Location ID: 387259



Photos 1 & 2. Taken along the access road, facing north. It does not appear that the access road has been reclaimed with evidence of contouring and grading issues.

Inspection Photos
Location Name: Schrader J8
Location ID: 387259




Photos 3 & 4. Taken near the well location, facing north (Photo 3; left) and east (Photo 4; right). The former well location does not appear to be progressing towards reclamation standards and regulations with evidence of non-uniform vegetation cover that is not reflective of the adjacent reference areas.

Inspection Photos
Location Name: Schrader J8
Location ID: 387259



Photos 5 & 6. Taken near the well location, facing south (Photo 5; left) and west (Photo 6; right). See comments in Photos 3 & 4 for additional information.

Inspection Photos
Location Name: Schrader J8
Location ID: 387259



Photos 7 & 8. A disturbance area southeast of the former well location, possibly a former drilling pit, tank battery, or production facility, is also experiencing non-uniform vegetation cover resulting in bare soils.

Inspection Photos
Location Name: Schrader J8
Location ID: 387259



Photo 9. Photo of the adjacent reference area south of the former well location.

Inspection Photos
Location Name: Schrader J8
Location ID: 387259



Photo 10. Google Earth historical aerial imagery (circa 10/1989) illustrating that the reported lat/long on the scout card for API 075-05062 (40.465150, -103.434530; red dot) differs from field observations and historical imagery, represented by the yellow pin (approx. 40.4658422, -103.4350519).