

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2025

Submitted Date:

06/05/2025

Document Number:

715202523**FIELD INSPECTION FORM**Loc ID 321696 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77069**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Randel, Jason	719-767-8851	jrandel@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207805	WELL	TA	05/25/2023	OW	017-06740	ARAPAHOE UNIT 131(43-25)	PA

General Comment:

SE Compliance Specialist Brian Welsh conducted a P&A Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective ActionL		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by cathodic rectifier		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date: _____		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Wire panel around cathodic rectifier and electric panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:	Remove deadmen and begin final reclamation process	Date:	07/04/2025
Type: Ancillary equipment	# 2		
Comment:	Cathodic rectifier and electric panel		
Corrective Action:	Remove ancillary equipment and begin final reclamation process	Date:	07/04/2025

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities											
Facility ID:	207805	Type:	WELL	API Number:	017-06740	Status:	TA	Insp. Status:	PA		
Cement											
Cement Contractor											
Contractor Name:					Franks Oilfield					Contractor Phone:	
Surface Casing											
Cement Volume (sx):										Circulate to Surface:	
Cement Fall Back:										Top Job, 1" Volume:	
Intermediate Casing											
Cement Volume (sxs):										Good Return During Job:	
Production Casing											
Cement Volume (sx):										Good Return During Job:	
Plugging Operations											
Depth Plugs(feet range):					2350/2130/1590/765					Cement Volume (sx):	295 SXS
Good Return During Job:					YES					Cement Type:	60/40 POZ
Comment:										<p>HALDE WATER, FRANKS OILFIELD SERVICE, CODELL WELL SERVICE. MIRU CODELL, RIH W/CICR TO 2350'. MIRU FRANKS, ATTEMPTED TO PUMP CMT DOWN TBG, PRESSURED UP TO 3500PSI. STUNG OUT OF CICR AND PUMPED 10BBLs WATER TO REVERSE OUT. STUNG BACK INTO CICR AND PRESSURED UP AGAIN. MIRU CODELL. STING OUT AND SWABBED EXCESS FLUID FROM TUBING, STAND BACK TBG AND REMOVE STINGER TO RIH W/OPEN ENDED TBG. SHUT DOWN AND WAIT ON ECMC ENGINEERS APPROVAL TO SET 5 SXS ABOVE CICR.</p> <p>AFTER APPROVAL, MIRU FRANKS, PUMPED 5SXS CMT ON CICR @ 2350' DISP W/1 BBL. MIRU CODELL, POOH WITH TBG. RIH W/CICR TO 2130'. MIRU FRANKS, TRIED TO EST RATE, PRESSURED UP TO 1,000PSI. STUNG OUT AND EST RATE OF 2BBLs/MIN @ 500 PSI. STUNG BACK INTO CICR EST RATE OF 2BBLs/MIN @ 1200PSI. PUMPED 70SXS THRU CICR W/5SXS ON TOP. MIRU CODELL, POOH W/TBG, RIH W/CICR TO 1590'. MIRU FRANKS, PUMP 30SXS THRU CICR W/5SXS ON TOP. MIRU CODELL, LAY DOWN TBG. MIRU FRANKS, BREAK CIRC, BULLHEAD 180SXS DOWN CSG W/CMT TO SFC, SI THE WELL.</p>	
Corrective Action:										Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12											

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404231439	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084431
715202530	Cementing operations	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084430