

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2025

Submitted Date:

06/05/2025

Document Number:

716301066

FIELD INSPECTION FORMLoc ID 334133 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
,		dnr_ecmc_engineering@state.co.us	
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259033	WELL	PR	03/01/2025	GW	071-07178	BULL FROG 23-7	PR
291208	WELL	PR	10/21/2007	CBM	071-09345	BULL FROG 23-7 TR	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: APPEARS TO BE UNUSED TANK BATTERY.		
Corrective Action:	IF PRODUCED WATER TANK IS NOT NECESSARY FOR THE OPERATION OF THIS WELL IT MUST BE REMOVED PER RULE 606. IF TANK IS NECESSARY FOR THE OPERATION OF THIS WELL A BERM MUST BE INSTALLED AROUND TANK PER RULE 603.o.	Date:	07/04/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	TR WELL		
Corrective Action:		Date:	
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	BOTH ARE ACCESSABLE		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLs	STEEL AST		37.271060,-104.717206	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	SEE HOUSE KEEPING FOR CORRECTIVE ACITON.				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	259033	Type:	WELL	API Number:	071-07178	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	NOTE: THE 1ST MIT PERFORMED ON 10/18/2019 WAS OVER 3 MONTHS PAST DUE, THE LAST MIT PERFORMED ON 4/17/2024 WAS DONE WITHIN 5 YEARS.								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		11/20/2011		Annual Brhd Completed?					
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:	FORM 4 ON FILE								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	291208	Type:	WELL	API Number:	071-09345	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		11/20/2011		Annual Brhd Completed?					
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:	FORM 4 ON FILE								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404230249	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083030
716301067	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083005