

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2025

Submitted Date:

06/05/2025

Document Number:

694500773

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
NEIDEL, KRIS 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Christian, Cody	970-902-0518	Cody.Christian@scoutep.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488590	SPILL OR RELEASE	CL	03/11/2025		-	GRAY B 17 Flowline	EI

**General Comment:**

On 6/4/25 ECMC staff, Kris Neidel inspected the Gray B17 spill, number 488590. Any corrective actions issued by ECMC in other inspections remain valid. Weather was 75 degrees and partly cloudy. The following was observed: the subsurface point of release had been backfilled, much of the impacted vegetation in the spill path appeared alive and free of hydrocarbon, there were a few areas of isolated hydrocarbon staining, less than one sq foot. Corrective Actions: remove areas of observable hydrocarbon staining with a shovel and bucket (or equivalent, large equipment is not necessary and may inflict more damage). See attached photos.

Inspected Facilities									
Facility ID:	488590	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental		
<b>Spill/Remediation:</b>		
Comment:	there were a few areas of isolated hydrocarbon staining, less than one sq foot.	
Corrective Action:	remove areas of observable hydrocarbon staining with a shovel and bucket (or equivalent, large equipment is not necessary and may inflict more damage).	Date: 06/26/2025
Emission Control Burner (ECB): _____		
Comment:	_____	
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404231032	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083868">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083868</a>
694500774	photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083861">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083861</a>