

## Inspection Photos

**Operator: LOCIN OIL CORPORATION- 51130**

**Location Name: COLUMBINE SPINGS #8-11-4-104 WDW**

**Location ID: 315617 API #: 05-103-08825**

**Inspection Date: 6/11/2025 Inspection Doc#: 693808828**



**Location overview looking E**



**Location overview looking S**



## Inspection Photos

**Operator: LOCIN OIL CORPORATION- 51130**

**Location Name: COLUMBINE SPINGS #8-11-4-104 WDW**

**Location ID: 315617 API #: 05-103-08825**

**Inspection Date: 6/11/2025 Inspection Doc#: 693808828**



**Injection wellhead housing**



**Wellhead inside housing**





## Inspection Photos

**Operator: LOCIN OIL CORPORATION- 51130**

**Location Name: COLUMBINE SPINGS #8-11-4-104 WDW**

**Location ID: 315617 API #: 05-103-08825**

**Inspection Date: 6/11/2025 Inspection Doc#: 693808828**



**Pump housing**



**Tank Battery**

## Inspection Photos

**Operator: LOCIN OIL CORPORATION- 51130**

**Location Name: COLUMBINE SPINGS #8-11-4-104 WDW**

**Location ID: 315617 API #: 05-103-08825**

**Inspection Date: 6/11/2025 Inspection Doc#: 693808828**



**Leaking valve on Produced Water/ Condensate tank**



**Produce Water/Condensate fluid level inside berms.**





## Inspection Photos

**Operator: LOCIN OIL CORPORATION- 51130**

**Location Name: COLUMBINE SPINGS #8-11-4-104 WDW**

**Location ID: 315617 API #: 05-103-08825**

**Inspection Date: 6/11/2025 Inspection Doc#: 693808828**



**Leaking berm liner on SE corner of tank berms**



**Spill area from leaking berms.**



## Inspection Photos

**Operator: LOCIN OIL CORPORATION- 51130**

**Location Name: COLUMBINE SPINGS #8-11-4-104 WDW**

**Location ID: 315617 API #: 05-103-08825**

**Inspection Date: 6/11/2025 Inspection Doc#: 693808828**



**Flowline riser with audible gas leak**



**Valve with audible gas leak.**

