

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2025

Submitted Date:

06/13/2025

Document Number:

713400856

FIELD INSPECTION FORM

Loc ID: 324459 Inspector Name: Popejoy, Dusty On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10515
Name of Operator: GUNNISON ENERGY LLC
Address: 999 18TH STREET SUITE 1755N
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 17 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Koch, Benjamin		bzkoch@blm.gov	
Energy, Gunnison		geops@oxbow.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211688	WELL	SI	03/01/2025	GW	051-06010	FEDERAL 10-90-32	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)

On 06/11/2025 at approximately 11:30 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD at Location ID #324459 in Gunnison County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Signs/Marker - Emergency Contact Number on all signs on location are not in service/not in compliance with CECMC rules with a CA date of 06/14/2025
2. Equipment - PRV vent line & Rupture disc vent line does not comply with CECMC pressure safety device rules with a CA date of 06/20/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Emergency Contact Number is not in service/not in compliance with CECMC rules		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Emergency Contact Number is not in service, additionally quarter/quarter section is illegible /not in compliance with CECMC rules		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Emergency Contact Number is not in service/not in compliance with CECMC rules		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Emergency Contact Number on all signs on location are not in service/not in compliance with CECMC rules		
Corrective Action:	Comply with CECMC 600 series rules		Date: 06/14/2025

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris		
Corrective Action:			Date:
Type	OTHER		
Comment:	Staining around heater on separator		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire on North side of location		

Corrective Action:		Date:	
Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	PRV vent line & Rupture disc vent line does not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	06/20/2025
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 211688 Type: WELL API Number: 051-06010 Status: SI Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Tracking Pad						
Berms						
		Ditches				
		Gravel				Sparse
Compaction						
		Sediment Traps				
		Berms				
Gravel						Sparse
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker & Equipment for corrective actions and Housekeeping for comments.	popejoyd	06/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400857	Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7094391