

# Interim Reclamation and Stormwater Inspection

June 12, 2025

Operator: COPPER LAND RESOURCES LLC - 10808

Location ID: 317308

Well Name: LINDA #2

Inspection Document #: 718600672

Washington County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LINDA #2  
Location ID: 317308



**Photo 1.** Looking south across tank battery.



**Photo 2.** Looking south across the east side of tank battery towards produced water pit. Undesirable weed kochia is present at location. Location is surrounded by active cropland.





Inspection Photos  
Location Name: LINDA #2  
Location ID: 317308



**Photo 3.** Picture taken near skim pit looking northwest. Gully erosion is present between produced water pit and skim pit (red circle).



**Photo 4.** Picture taken at tank behind separator. Erosion is beginning to wash out underneath the north edge of the tank.





Inspection Photos  
Location Name: LINDA #2  
Location ID: 317308



**Photo 5.** Looking south across the eastern produced water pit. The wall on this edge of pit is approximately 18" above water level.




**Photo 6.** Looking south down access road to wellhead. Undesirable weed kochia is present.





Inspection Photos  
Location Name: LINDA #2  
Location ID: 317308



**Photo 7.** Looking southeast at wellhead.



**Photo 8.** Looking north across wellhead area.





Inspection Photos  
Location Name: LINDA #2  
Location ID: 317308



**Photo 9.** Looking east along the south side of the location. Location is surrounded by cropland.



**Photo 10.** Looking north along the east side of location. See photo 9 comments.

