

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2025

Submitted Date:

06/13/2025

Document Number:

708906743

FIELD INSPECTION FORM

Loc ID 334623 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 26 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268811	WELL	PR	02/19/2004	GW	045-09298	GMR 4-11C (K4C)	PR
268825	WELL	PR	02/19/2004	GW	045-09300	GMR 33-14 (K4C)	PR
272936	WELL	PR	02/20/2004	GW	045-10196	GMR 4-11BX (K4C)	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)
On 06/11/2025 at approximately 13:46 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at QB ENERGY OPERATING LLC GMR 4-11C (K4C) Pad Location # 334623 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

- Signs/Marker - Emergency phone # on wellhead signs incorrect/# is disconnected & not in service with a CA date of 07/13/2025
- Inspected Facilities - GMR 33-14 (K4C) & GMR 4-11BX (K4C) wells lack wellbore diagrams with a CA date of 07/13/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
This is a summary of inspection/audit report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Signs at separators Emergency phone # on wellhead signs Incorrect/# is disconnected & not in service/not in compliance with CECMC rules		
Corrective Action:	Comply with CECMC 600 series rules		Date: 07/13/2025
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Small amount of weeds in secondary containment		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment: Chemical tank			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment: GMR 33-14 (K4C) well surface casing BH has no form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. GMR 4-11C (K4C) & GMR 4-11BX (K4C) wells surface casing bradenheads equipped with pressure transducers, bradenhead valves are accessible.			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment: Summit Midstream			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment: All wells on plunger lift			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment: Marked			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment: GMR 33-14 (K4C) IC BH equipped with pressure transducer, valve is accessible			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			

Comment:	Centralized containment
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	OTHER	STEEL AST		

Comment:	Tanks equipped with telemetry
Corrective Action:	Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	250 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			

Comment:	Centralized containment
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 268811 Type: WELL API Number: 045-09298 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunegr lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 268825 Type: WELL API Number: 045-09300 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - GMR 4-11BX (K4C) well also lacks wellbore diagram.
Additionally Drilling Completion Report, Completed Interval Report & Downhole Schematic submitted by operator for the GMR 33-14 (K4C) well appear to contain multiple inaccuracies/errors

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17 & additionally contact CECMC Engineering Group to discuss additional issues noted above. Date: 07/13/2025

BradenHead

Date of Last Brhd Test: 05/23/2024 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual testing was not completed on intermediate casing in 2021, 2022, 2023 or 2024/not in compliance with CECMC 400 series rules

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272936 Type: WELL API Number: 045-10196 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift
Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small amount of light compaction
Berms						
		Compaction				Light compaction in some sections
Ditches						
				Material Handling And Spill Prevention		Chemical tank containment
		Gravel				Sparse to none
Gravel						Sparse to none in some areas
		Ditches				
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker & Inspected Facilities for corrective actions	smelserw	06/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906744	Inspection/Audit 708906743 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095587
708906745	Inspection/Audit 708906743 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095588