

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

06/09/2025

Document Number:

707801638

FIELD INSPECTION FORM

Loc ID 322404 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 19 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|------------------------------|---------------------------------|
| , Vision | | mrinc20@maralexinc.com | |
| , Vision | | pbechtolt@maralexinc.com | |
| Haverkamp, Curtis | | curtis.haverkamp@state.co.us | |
| , Vision | | mollieo@maralexinc.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 210419 | WELL | TA | 11/01/2020 | GW | 045-06175 | BALDY CREEK UNIT 1-17 | TA |

General Comment:

[CECMC Inspection Report Summary](#)
On Tuesday 6/3/2025, I, Inspector Scott Ramsey, conducted a follow up inspection/audit at Vision Baldy Creek 1-17, at Location # 322404 in Garfield county Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed well shut it. Last MIT was preformed 7/14/2023. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

C/A's from previous inspection document # 708904948 have not been addressed therefore all C/A's remain the same.
During this inspection the following compliance issues were observed:

- Signs/Marker - Tank label on production tank contains inaccurate info/does not comply with CECMC rules with a CA date of 12/02/2024.
- Housekeeping - Open ended piping/available for entry by wildlife/wildlife hazard with a CA date of 11/09/2024
- Equipment - Meter calibration info not conspicuously posted with a CA date of 12/02/2024
- Equipment - Open ended load line with a CA date of 11/09/2024
- Tanks & Berms - Secondary containment is insufficient/does not comply with CECMC secondary containment rules with a CA date of 11/22/2024
- Location is over grown with vegetation.
Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

| Signs/Marker: | | |
|----------------------|---|-------------------------|
| Type | TANK LABELS/PLACARDS | |
| Comment: | Tank label on production tank contains inaccurate info/does not comply with CECMC rules | |
| Corrective Action: | Comply with CECMC tank labeling rules | Date: <u>12/02/2024</u> |
| Type | OTHER | |
| Comment: | Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank. | |
| Corrective Action: | | Date: |
| Type | WELLHEAD | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type | BATTERY | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | |
|----------------------------------|---------------------|-------------|
| Emergency Contact Number: | | |
| Comment: | <u>970-563-0082</u> | |
| Corrective Action: | | Date: _____ |

| Good Housekeeping: | | |
|---------------------------|---|-------------------------|
| Type | WEEDS | |
| Comment: | Weeds encroaching on equipment in multiple areas | |
| Corrective Action: | Remove weeds | Date: <u>07/06/2025</u> |
| Type | OTHER | |
| Comment: | Open ended piping/available for entry by wildlife/wildlife hazard | |
| Corrective Action: | Comply with CECMC wildlife rules | Date: <u>11/09/2024</u> |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Equipment: | | | corrective date |
|---------------------|--|--|-----------------|
| Type: Bradenhead | # 1 | | |
| Comment: | No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Summit Midstream | | |

| | | | |
|-----------------------------------|---|-------|------------------|
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter calibration info not conspicuously posted | | |
| Corrective Action: | The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times. | | Date: 12/02/2024 |
| Type: Horizontal Heated Separator | # | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Open load lines | | |
| Corrective Action: | All load lines will be capped or plugged | | Date: 11/09/2024 |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLs | HEATED STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|------------------|
| Earth | Inadequate | Walls Insufficient | Base Insufficient | Inadequate |
| Comment: | Secondary containment is insufficient/does not comply with CECMC secondary containment rules. Additionally secondary containment is overrun with vegetation & compromised. | | | |
| Corrective Action: | Comply with CECMC secondary containment rules | | | Date: 11/22/2024 |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 210419 Type: WELL API Number: 045-06175 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: [Shut In](#)
[Last produced September 2009](#)
[Last MIT 06/13/2023 - document # 403444969](#)

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|--|
| | | Culverts | | | | |
| | | Gravel | | | | Sparse to none in areas |
| Ditches | | | | | | |
| Culverts | | | | | | |
| Other | | | | | | Cut slope showing signs of lack of stabilization |
| | | Ditches | | | | |
| Gravel | | | | | | Sparse to none in areas |
| Compaction | | | | | | Small amount of light compaction |
| | | Compaction | | | | Light compaction in some areas |

Comment: [Cut slope showing some signs of lack of stabilization](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404234018 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087962 |
| 707801643 | Photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087959 |