



- Inadequate secondary containment for the 210-bbl open top fiberglass produced water storage tank.
- Wildlife protection equipment (netting) is missing on the 210-bbl open top fiberglass produced water storage tank (empty at time of inspection)
- Missing NFPA Placard
- Weeds



-Wildlife protection equipment (netting) is missing on the 210-bbl open top fiberglass produced water storage tank (empty at time of inspection)



- Inadequate secondary containment for the 100-bbl open top fiberglass produced water storage tank
- Wildlife protection equipment (netting) is torn/falling on the 100-bbl open-top fiberglass produced water storage tank
- Peeling/faded NFPA Placard
- Stained soil observed around the base of the 100-bbl open-top fiberglass produced water storage tank
- Weeds



- Adjacent property - Fenced in storage area with oil and gas equipment (N/NE) of tank battery
- Stained soil observed around the base of the 100-bbl open-top fiberglass produced water storage tank
- Inadequate secondary containment for the 100-bbl open top fiberglass produced water storage tank
- Weeds



Weeds



- Wildlife protection equipment (netting) installed on the 100-bbl open top fiberglass produced water storage tank is torn/falling and requires maintenance/repair
- Weeds



-Stained soil observed around the base of the 100-bbl open-top fiberglass produced water storage tank
-Weeds



- Inadequate secondary containment for the 100-bbl and 210-bbl open top fiberglass produced water storage tanks
- Wildlife protection equipment (netting) was missing on the 210-bbl open-top fiberglass produced water storage tank (empty at time of inspection)
- Wildlife protection equipment (netting) was torn/falling on the 100-bbl open-top fiberglass produced water storage tank
- Stained soil observed around the base of the 100-bbl open-top fiberglass produced water storage tank
- Weeds



- Inadequate secondary containment for the 100-bbl and 210-bbl open top fiberglass produced water storage tanks
- Weeds

WGS84 37.38305,
±11ft-102.21428

Δ m 1177 Δ °, T N355
±3m ±11



ECMC
Environmental
Field Inspection



Mama Bear Tank Battery (479908)
04-Jun-25 12:04:25

Weeds/Debris.

WGS84 37.38311,
±16ft -102.21432

Δ ^m_{±4m} 1178  °,T
±11 NE33



ECMC
Environmental
Field Inspection



Mama Bear Tank Battery (479908)

© 04-Jun-25 12:04:44



- Inadequate secondary containment for the 100-bbl and 210-bbl open top fiberglass produced water storage tanks
- Weeds



- Inadequate secondary containment for the 100-bbl and 210-bbl open top fiberglass produced water storage tanks
- Wildlife protection equipment (netting) was missing on the 210-bbl open-top fiberglass produced water storage tank (empty at time of inspection)
- Weeds
- Unused equipment (piping) stored along N/NE adjacent property fencing



- Weeds
- Unused equipment (piping) stored along N/NE adjacent property fencing