

WGS84 $\pm 12\text{ft}$ 38.69422, -102.41899 $\wedge^m_{\pm 3\text{m}}$ 1325 $\triangle^{\circ, T}_{\pm 10}$ E94



ECMC
Environmental
Field Inspection



Nininger Wellhead
© 30-May-25 11:48:50 AM
ECMC Environmental Inspection

Looking at former wellhead from the access road.

WGS84
±16ft

38.69422, -102.41867

m
±4m

1324

°T
±11

E85



The excavation at the former wellhead has been backfilled.

WGS84 $\pm 9\text{ft}$ 38.69422, -102.41857 $\pm 3\text{m}$ 1326 ± 11 E97



ECMC
Environmental
Field Inspection



Nininger Wellhead
© 30-May-25 11:49:35 AM
ECMC Environmental Inspection

Ground subsidence is visible in the vicinity of the former wellhead.

WGS84 38.69407, -102.41842 Δ $\pm 9\text{ft}$ $\pm 3\text{m}$ 1327 ± 11 SE112



ECMC
Environmental
Field Inspection



Nininger Wellhead
© 30-May-25 11:50:08 AM
ECMC Environmental Inspection

An unmarked soil stockpile is visible next to a small excavation southeast of the former wellhead. No stormwater BMPs or liner is visible. No fencing is visible surrounding the excavation.

WGS84 $\pm 13\text{ft}$ 38.69403, -102.41832 \wedge^m $\pm 3\text{m}$ 1328 $\triangle^{\circ, T}$ ± 11 W281



ECMC
Environmental
Field Inspection



Nininger Wellhead
30-May-25 11:50:49 AM
ECMC Environmental Inspection

Debris is visible within the excavation. Animal burrows are visible within the stockpile.

WGS84 $\pm 15\text{ft}$ 38.69403, -102.41836 $\pm 4\text{m}$ 1327 ± 11 E90



ECMC
Environmental
Field Inspection



Nininger Wellhead
© 30-May-25 11:51:02 AM
ECMC Environmental Inspection