




ECMC
Environmental
Field Inspection



Lowe 1B SWD Well
© 30-May-25 01:29:36 PM
ECMC Environmental Inspection

An excavation remains open surrounding the former wellhead. The wellhead has been cut and capped. A segment of flowline is visible within the open excavation. Weeds have grown within the excavation.



A segment of white plastic pipe is visible within the excavation; the pipe is uncapped. A segment of flowline is visible within the excavation; valves remain attached and a bull plug has been installed. The base of the excavation sidewalls appear to have partially eroded.

WGS84 39.09372, -102.52815 Δ m 1360 Δ T S194
 ± 14 ft ± 4 m ± 12



Lowe 1B SWD Well
30-May-25 01:31:13 PM
ECMC Environmental Inspection

Uncapped white plastic pipe.

WGS84 $\pm 13\text{ft}$ 39.09375, -102.52815 $\Delta^m_{\pm 4m}$ 1361 $\triangle^{\circ,T}_{\pm 12}$ SW196



Lowe 1B SWD Well
© 30-May-25 01:31:27 PM
ECMC Environmental Inspection

ECMC
Environmental
Field Inspection



The well casing and a segment of white plastic pipe are visible adjacent to the wellhead excavation.



ECMC
Environmental
Field Inspection



Lowe 1B SWD Well
© 30-May-25 01:32:57 PM
ECMC Environmental Inspection

Vegetation appears depressed in an area east of the former wellhead.



An unmarked soil stockpile and a small excavation are visible southeast of the former wellhead.

WGS84 39.09392, -102.52792 Δ^m 1359 $\pm 7ft$ $\pm 3m$ ± 12 W271



ECMC
Environmental
Field Inspection



Lowe 1B SWD Well
© 30-May-25 01:33:51 PM
ECMC Environmental Inspection

Weeds are visible within the small excavation.

