

WGS84 39.09208, -102.52134 $\Delta^m_{\pm 3m}$ 1353 $\triangle^{\circ,T}_{\pm 10}$ W280



ECMC
Environmental
Field Inspection



Lowe B-2 TB
© 30-May-25 01:43:57 PM
ECMC Environmental Inspection

An uncapped light green riser is visible between fence posts in the background; weeds surrounding metal pipes/risers are visible in the foreground.

WGS84 39.09203, -102.52149 $\Delta^m_{\pm 3m}$ 1354 $^{\circ},T_{\pm 11}$ NE16
±13ft



ECMC
Environmental
Field Inspection



Lowé B-2 TB
© 30-May-25 01:49:03 PM
ECMC Environmental Inspection

The ground surface surrounding the light green riser appears to have subsided; a void is visible.


WGS84 $\pm 12\text{ft}$ 39.09233, -102.52141 $\pm 3\text{m}$ 1354 ± 11 °T E84



Lowe B-2 TB
© 30-May-25 01:46:33 PM
ECMC Environmental Inspection

Multiple pin flags are visible throughout the location and appear to have been placed adjacent to areas of ground disturbance.

WGS84 $\pm 10\text{ft}$ 39.09233, -102.52141 $\Delta^{\text{m}}_{\pm 3\text{m}}$ 1354 $\triangle^{\circ, \text{T}}_{\pm 11}$ N353



ECMC
Environmental
Field Inspection



Lowe B-2 TB
© 30-May-25 01:47:01 PM
ECMC Environmental Inspection

Example of the labeling visible on many of the pin flags.



WGS84
±10ft

39.09226, -102.52136

m
±3m

1354

±11

W271

ECMC
Environmental
Field Inspection



Lowe B-2 TB

© 30-May-25 01:47:23 PM

ECMC Environmental Inspection

Multiple trenches/small excavations are visible on location; no fencing is visible.



WGS84 39.09221, -102.52136 1354 W268
±13ft ±4m ±11

ECMC
Environmental
Field Inspection



Lowe B-2 TB
© 30-May-25 01:47:34 PM
ECMC Environmental Inspection

An uncapped riser is visible within one of the trenches/excavations.



Lowe B-2 TB
30-May-25 01:47:46 PM
ECMC Environmental Inspection

The uncapped riser appears to consist of fiberglass.



WGS84 39.09217, -102.52137 Δ ± 13 ft ± 4 m 1354 ± 11 W267

ECMC
Environmental
Field Inspection



Lowe B-2 TB
© 30-May-25 01:48:03 PM
ECMC Environmental Inspection

A white horizontal line/pipe is visible within another trench/excavation.

WGS84 39.09213, -102.52142 Δ m 1355 Δ °, T NW313
±15ft ±4m ±11



ECMC
Environmental
Field Inspection



Lowe B-2 TB
© 30-May-25 01:48:44 PM
ECMC Environmental Inspection

An uncapped metal riser is visible on location.