

WELL NAME: WILD TURKEY 23-5, API #: 071-06624, INSP. # 716301120



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: UNUSED EQUIPMENT (1" RISER NOT IN US AND NOT MARKED WHAT ITS USED FOR i.e. gas or water). **USE, REMOVE OR LABEL RISER PER RULE 606. CA DATE 6-25-25.**





PHOTO 5: TRASH AND OR DEBREE (INSULATION ON SOUND WALLS IS DETERIORATING AND SPREADING ON AND AROUND LOCATION). PICK UP ALL TRASH ON AND AROUND LOCATION AND SECURE OR REPLACE INSULATION PER RULE 606. CA DATE 6-25-2025.





PHOTO 6: AREA OF IMPACTED SOIL AROUND WELLHEAD APPEARS TO BE FROM LEAKING DRIVEHEAD MOTOR SHOWN IN NEXT PHOTO. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 6-25-2025.



WGS84
±30ft


37.28527, -104.69751

ft
±19ft

7413

°M
±21

NE75



HYDRALIC
OIL DRIP

Colorado Oil & Gas Conservation commission
© 16-Jun-25 10:51:35

PHOTO 7: PHOTO SHOWING LEAKING DRIVEHEAD MENTIONED IN PREVIOUS PHOTO.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 8: AREA OF IMPACTED SOIL AROUND PRIME MOVER ENGINE SKID (IMPACTED SOILS ON OTHER SIDES OF SKID ALSO). Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 6-25-2025.



PHOTO 9: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 6-25-2025.



PHOTO 10: PART OF THE WIRES HAVE BEEN REMOVED FROM FENCE. REPAIR FENCE PER 1002 SERIES RULES. CA DATE 6-25-2025.

