

WGS84 $\pm 16\text{ft}$ 40.09674, -104.88928 $\Delta_{\pm 4\text{m}}^{\text{m}}$ 1531 $\triangle^{\circ, \text{T}}_{\pm 10}$ SE129



ECMC
Environmental
Field Inspection



Suckla C#3 Spill
© 16-Jun-25 03:31:07 PM
ECMC Environmental Inspection

Photo taken adjacent to Operator equipment and the spill location. Horses are visible in the background. The pasture in which the spill was discovered remains in use. Metal fence panels from the pictured coral were moved by the Operator to encompass the spill area.



Suckla C#3 Spill
© 16-Jun-25 03:33:29 PM
ECMC Environmental Inspection

Operator personnel were in the process of installing metal panel fencing around the excavation. The excavation and stockpile were fully encompassed by the fencing at the conclusion of the inspection.

The pumping unit of the well associated with the spill (Suckla Farms C 3, API # 05-123-08882) is visible in the background at the left side of the photo.



ECMC
Environmental
Field Inspection



Suckla C#3 Spill
© 16-Jun-25 03:32:13 PM
ECMC Environmental Inspection

Operator personnel were on location at the time of inspection. A small excavation has been opened at the spill location. Excavated soil has been stockpiled adjacent to the excavation; no markings or liners were visible at the stockpile.



WGS84
±16ft

40.09674, -104.88920



m
±4m

1530



°T
±10

NE61

ECMC
Environmental
Field Inspection



Suckla C#3 Spill
© 16-Jun-25 03:31:19 PM
ECMC Environmental Inspection

Black staining was visible in situ.



Black staining was visible in situ.