

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8523 Entrance to location



Photo # 8550 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8525 Location



Photo # 8541 Location



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8547 Location



Photo # 8548 Location



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8559 Location



Photo # 8566 NW corner of location



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8567 NE corner of location



Photo # 8568 SE corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8569 SW corner of location



Photo # 8536 Staining



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8538 Staining



Photo # 8539 Staining



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



**Photo # 8543 Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules**



**Photo # 8545 Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules**



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 44-23 PAD

Location ID: 429938

Date: 06/16/2025



Photo # 8558 Unused hose

