

**Inspection Photos**  
**Location: Frontera Unit Gas Plant**  
**Location ID: 480729, Spill ID 489242**



**Photo 1- Facility Placard**



**Inspection Photos**  
**Location: Frontera Unit Gas Plant**  
**Location ID: 480729, Spill ID 489242**



**Photo 2 – Spill Excavation**



**Photo 3 – Stained soils**



**Photo 4 – Inadequate Berming**

**Inspection Photos**  
**Location: Frontera Unit Gas Plant**  
**Location ID: 480729, Spill ID 489242**



**Photo 5 – Stockpiles**



**Photo 6 – Inadequate earthen berms**



**Photo 7 – Compromised Liner**

**Inspection Photos**  
**Location: Frontera Unit Gas Plant**  
**Location ID: 480729, Spill ID 489242**



**Photo 8 – Open Excavation**



**Photo 9 – Inadequate  
fencing**



**Photo 10 – Open Excavation**