

Inspection Photos

LOC ID: 441082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/16/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing northwest toward the location. Much of the location consists of undesirable weeds and bare soils.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 441082 | Date: 6/16/2025

Inspection Photos



Photo 2. Drone aerial photo facing toward the flowline pipe that remains at the southeast corner. There is no signage posted at this equipment.



Inspection Photos



Photo 3. Drone aerial photo facing southwest toward the location. Much of the location consists of undesirable weeds and bare soils. It appears there are impacted soil from historical spills from the abandoned compressor station.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 441082 | Date: 6/16/2025

Inspection Photos



Photo 4. The red arrow points to the gravel pile that still remains at the northwest corner and is full of undesirable weeds (Kochia).



Inspection Photos



Photo 5. Drone aerial photo facing northeast toward the location. Area of disturbance is approximately 1 acre in size.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 441082 | Date: 6/16/2025

Inspection Photos



Photo 6. View of adjacent surrounding vegetation which consists of Fourwing salt brush community.



Inspection Photos



Photo 7. There was a cleanout junction 1850 ft. north of the pipeline previously observed. The cleanout junction is associated with the former gas compressor station and must be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 441082 | Date: 6/16/2025