

Inspection Photos

API: 009-06573

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 6/16/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. . Facing east along the former access road. The road has not fully established perennial vegetation and there are noxious weeds along the road.



Inspection Photos



Photo 2. Facing east along the former access road. The road has not fully established perennial vegetation and there are noxious weeds along the road.



Inspection Photos



Photo 3. Facing east toward the abandoned wellsite. The location has not been reclaimed.



Inspection Photos



Photo 4. Facing north at the location. There is bare soil at the well site which appears to be impacts from a historic spill . This area is approximately 50'x50'. There are noxious weed throughout the location (Field bind weed – white flower).



Inspection Photos



Photo 5. Facing south toward the surrounding reference area.

