

Final Reclamation and Stormwater Inspection

June 16, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 335769

Well Name: ERIE CHAMPLIN B UNIT #1

Inspection Document #: 718600688

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #1
Location ID: 335769



Photo 1. Looking west down the access road. A gate is installed.



Photo 2. Picture taken at mid point of access road looking south towards location.



Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #1
Location ID: 335769



Photo 3. Looking southeast across the location. No oil and gas equipment remains. Undesirable weed Kochia is dominant throughout the location. Some desirable perennial vegetation is present.



Photo 4. Looking northwest across the location. See photo 3 comments.



Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #1
Location ID: 335769



Photo 5. Looking north from the wellbore. Undesirable weed kochia is dominant throughout the location. Some desirable vegetation is present, but large areas of the location have little to no desirable vegetation establishment.



Photo 6. Looking west from the wellbore. See photo 5 comments.



Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #1
Location ID: 335769



Photo 7. Looking south from the wellbore. See photo 5 comments.



Photo 8. Looking east from the wellbore. See photo 5 comments.



Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #1
Location ID: 335769



Photo 9. Looking north across the former tank battery on the north side of the location.



Photo 10. Reference vegetation to the west of the well location.

Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #1
Location ID: 335769



Photo 11. Aerial photo taken 09/21/1972. It appears the majority of the access road was pre existing prior to oil and gas development (green arrows).