

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2025

Submitted Date:

06/19/2025

Document Number:

701104209

**FIELD INSPECTION FORM**Loc ID 335538 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291065	WELL	PR	01/01/2025	GW	045-14284	VALLEY FARMS F2	EG
291066	WELL	PR	11/01/2023	GW	045-14285	VALLEY FARMS F3	EG
291067	WELL	PR	07/11/2013	GW	045-14286	VALLEY FARMS F5	EG
291070	WELL	IJ	08/01/2024	DSPW	045-14287	VALLEY FARMS F4	EG
291071	WELL	AL	09/26/2014	LO	045-14288	VALLEY FARMS F6	EG
291072	WELL	PR	09/17/2013	GW	045-14289	VALLEY FARMS F7	EG
291073	WELL	PR	04/19/2010	GW	045-14290	VALLEY FARMS F1	EG
296414	WELL	PR	12/06/2009	GW	045-16011	VALLEY FARMS F8	EG
296415	WELL	PR	07/11/2013	GW	045-16012	VALLEY FARMS FEDERAL F14	EG
301818	WELL	PR	04/04/2013	GW	045-18286	Valley Farms F-1H	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection

Unused flowline risers are missing OOSLAT tags. One riser with out isolation at tank battery berm.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Flow Line	#				
Comment:		Unused flowline risers are missing OOSLAT tags. One riser with out isolation at tank battery berm.			
Corrective Action:		Comply with 1100 Rule Series		Date: 07/04/2025	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 291065	Type: WELL	API Number: 045-14284	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291066	Type: WELL	API Number: 045-14285	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291067	Type: WELL	API Number: 045-14286	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291070	Type: WELL	API Number: 045-14287	Status: IJ	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291071	Type: WELL	API Number: 045-14288	Status: AL	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291072	Type: WELL	API Number: 045-14289	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291073	Type: WELL	API Number: 045-14290	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296414	Type: WELL	API Number: 045-16011	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296415	Type: WELL	API Number: 045-16012	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301818	Type: WELL	API Number: 045-18286	Status: PR	Insp. Status: EG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104210	Inspection 701104209 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7102826">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7102826</a>