

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2025

Submitted Date:

06/19/2025

Document Number:

701104211

FIELD INSPECTION FORMLoc ID 335542 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288407	WELL	PR	01/01/2025	GW	045-13227	VALLEY FARMS E5	EG
288408	WELL	PR	01/01/2025	GW	045-13226	VALLEY FARMS E6	EG
288411	WELL	PR	01/22/2010	GW	045-13223	VALLEY FARMS E9	EG
288412	WELL	PR	10/08/2013	GW	045-13222	VALLEY FARMS E10	EG
288413	WELL	PR	01/05/2010	GW	045-13221	VALLEY FARMS E11	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection

Unused flowline risers are missing OOSLAT tags.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Flow Line	#				
Comment:		Unused flowline risers are missing OOSLAT tags.			
Corrective Action:		Comply with 1100 Rule Series		Date: 07/04/2025	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities				
Facility ID: 288407	Type: WELL	API Number: 045-13227	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 288408	Type: WELL	API Number: 045-13226	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 288411	Type: WELL	API Number: 045-13223	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 288412	Type: WELL	API Number: 045-13222	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 288413	Type: WELL	API Number: 045-13221	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104212	Flowline integrity inspection 701104211 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7102827