

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8631 Entrance to location



Photo # 8716 Battery sign lacks well info/not in compliance with CECMC rules

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8633 Location



Photo # 8635 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8668 Location



Photo # 8714 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8667 Chemical tank - Equipment does not appear to be in operators Form 2A or a Form 4 Sundry as required by CECMC rules.



Photo # 8731 Air compressor - Equipment does not appear to be in operators Form 2A or a Form 4 Sundry as required by CECMC rules.

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8732 SW corner of location



Photo # 8733 SE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8734 NE corner of location



Photo # 8735 NW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8660 Wellhead sign is not legible



Photo # 8693 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8694 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8700 Unused flowline does not comply with CECMC 600 & 1100 series rules

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8702 Unused flowline does not comply with CECMC 600 & 1100 series rules



Photo # 8715 2ND Battery sign not legible

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8724 Open ended load line



Photo # 8728 Suspected leaks on tank 1 production tank/tank appears to lack integrity

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



**Photo # 8730 Suspected leaks on tank 1 production
tank/tank appears to lack integrity**

