

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

06/13/2025

Document Number:

718600672

**FIELD INSPECTION FORM**Loc ID 317308 Inspector Name: Dunnam, Anthony On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10808

Name of Operator: COPPER LAND RESOURCES LLC

Address: 9470 HOMESTEAD DR

City: FREDERICK State: CO Zip: 80504

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email              | Comment |
|--------------|-------|--------------------|---------|
| Jany, Josh   |       | jdjany@hotmail.com |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|---------------------|-------------|
| 237995      | WELL     | PR     | 04/01/2021  | OW         | 121-10498 | LINDA 2             | RI          |
| 317308      | LOCATION | AC     |             |            | -         | LINDA-62S52W 30NENE | RI          |

**General Comment:**

This is an Interim Reclamation and Stormwater Inspection.

|  |   |        |  |             |
|--|---|--------|--|-------------|
| Location   |   |        |  |             |
| Overall Good: <input type="checkbox"/>                 |   |        |  |             |
| Emergency Contact Number:                              |   |        |  |             |
| Comment:   |   |        |  | Date: _____ |
| Corrective Action:                                     |   |        |  |             |
| Good Housekeeping:                                     |   |        |  |             |
| Type   | WEEDS   |        |  |             |
| Comment:   | Undesirable weed kochia is present throughout the location.<br>Comply with Rule 606.c. Control weeds on location. |        |  |             |
| Corrective Action:                                     |   |        |  | Date:       |
| Overall Good: <input type="checkbox"/>                 |   |        |  |             |
| Spills:  |   |        |  |             |
| Type   | Area  | Volume |  |             |
| In Containment: No                                     |   |        |  |             |
| Comment:   |   |        |  |             |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |  |             |
| Venting:   |   |        |  |             |
| Yes/No   |   |        |  |             |
| Comment:   |   |        |  |             |
| Corrective Action:                                     |   |        |  | Date:       |
| Flaring:   |   |        |  |             |
| Type   |   |        |  |             |
| Comment:   |   |        |  |             |
| Corrective Action:                                     |   |        |  | Date:       |

| Inspected Facilities   |        |       |          |             |           |         |    |               |    |
|--|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 237995 | Type: | WELL     | API Number: | 121-10498 | Status: | PR | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |
| Facility ID:   | 317308 | Type: | LOCATION | API Number: | -         | Status: | AC | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established Pass

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment The location is surrounded by active cropland. Location size has been reduced.

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                  |                 |                         |                       |               |                          |         |

Comment:

Erosion was observed around the base of the southern tank on location. Gulley erosion is present between the skim pit and produced water pit. See attached pictures.

Corrective Action:

Comply with Rule 1002.f. Repair and stabilize soil around tanks. Repair and stabilize soil near the skim pit.

Date:

Pits:

☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404240902    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095459">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095459</a> |
| 718600673    | Inspection Photos    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095458">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095458</a> |