

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2025

Submitted Date:

06/16/2025

Document Number:

717100251

**FIELD INSPECTION FORM**

Loc ID: 321926 Inspector Name: Rollins, Grace On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10634  
Name of Operator: P O & G OPERATING LLC  
Address: 5847 SAN FELIPE SUITE 3200  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
RANDO, CHRIS		christopher_rando@pogresources.com	All Inspections
Nash, Charlotte	281.543.3606	charlotte_nash@pogresources.com	Production and Regulatory
Waggoner, Kyle		kyle.waggoner@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Hudson, Glenn	713-589-8186	glenn_hudson@pogresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208562	WELL	PR	11/25/1995	OW	017-07497	LOWE 1-2R	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site Name: Lowe #1-2R Wellhead  
Wellhead API #: 05-017-07497  
Date of Inspection: 05/30/2025  
Weather: Sunny, 71°F

Spill is located within or adjacent to:  
-Crop land (immediately adjacent, all directions)  
-Lesser Prairie Chicken Estimated Occupied Range High Priority Habitat

Current site status:  
-Signage with emergency contact number was visible.  
-Petroleum hydrocarbon fluid residue was visible on the wellhead and connections. Black staining is visible on the plastic tank adjacent to the wellhead.  
-Stained soil was visible adjacent to the wellhead. A petroleum hydrocarbon odor was observed when the stained soil was disturbed.

See attached corrective actions.

<b>Location</b>			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type			
Comment:	Portions of the sign including, the API number, are illegible.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Signage with emergency contact number was visible.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
	WELLHEAD		
Comment:	Stained soil was visible adjacent to the wellhead. A petroleum hydrocarbon odor was observed when the stained soil was disturbed.		
Corrective Action:	Comply with ECMC Rules. Operator shall immediately control and contain spills/releases and investigate, clean up and document impacts per Rule 912.a. Note: for any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation and waste disposal manifests) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR. Additionally, Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules.		Date: <u>07/16/2025</u>
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type:		#	corrective date
Comment:	Petroleum hydrocarbon fluid residue was visible on the wellhead and connections. Black staining is visible on the plastic tank adjacent to the wellhead.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>07/01/2025</u>
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 208562 Type: WELL API Number: 017-07497 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404242158	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097021">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097021</a>
717100258	ECMC Photo Log - Lowe #1-2R Wellhead - 05.30.2025	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097014">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097014</a>