

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2025

Submitted Date:

06/16/2025

Document Number:

717100253**FIELD INSPECTION FORM**Loc ID 324937 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10634Name of Operator: P O & G OPERATING LLCAddress: 5847 SAN FELIPE SUITE 3200City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hudson, Glenn	713-589-8186	glenn_hudson@pogresources.com	<a href="#">All Inspections</a>
Nash, Charlotte	281.543.3606	charlotte_nash@pogresources.com	<a href="#">Production and Regulatory</a>
RANDO, CHRIS		christopher_rando@pogresources.com	<a href="#">All Inspections</a>
Sanchez, Chris		chris.sanchez@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488679	SPILL OR RELEASE	AC	12/10/2024		-	Lowe 1B SWD Well	EI

**General Comment:**

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 488679 and Remediation Project # 34664. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill Name: Lowe 1B SWD Well

Spill ID: 488679

Remediation Project #: 34664

Wellhead API #: 05-063-06186

Reported Date of Discovery: 05/13/2024

Date of Inspection: 05/30/2025

Weather: Sunny, 77°F

Current site status:

- An excavation remains open surrounding the former wellhead. The wellhead has been cut and capped.
- A segment of flowline was visible within the open excavation; valves remain attached and a bull plug has been installed.
- A segment of white plastic pipe was visible within the excavation; the pipe is uncapped.
- The well casing and a segment of white plastic pipe were visible adjacent to the wellhead excavation.
- The base of the excavation sidewalls appeared to have partially eroded.
- Weeds have grown within the excavations.
- Stockpiled soil utilized as a berm surrounded the open excavation. No fencing was visible.
- An unmarked soil stockpile and a small excavation were visible southeast of the former wellhead. No stormwater BMPs or liners were visible.
- Vegetation appears depressed in an area east of the former wellhead.

See attached corrective actions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds were visible within the open excavations.		
Corrective Action:	Comply with Rule 606.		Date: 06/23/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Stockpiled soil utilized as a berm surrounded the open excavation at the former wellhead. No fencing was visible at the excavations.		
Corrective Action:	Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.		Date: 06/30/2025

**Equipment:**

Type: Flow Line	#		corrective date
Comment:	Improper abandonment of flowline or crude oil transfer line per 1105.e.(4). A segment of flowline is visible within the excavation; valves remain attached and a bull plug has been installed.		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.e.(4).		Date: 07/16/2025

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	488679	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation Project # 34664 was created for the plugging and abandonment of the LOWE 1-B wellhead and decommissioning of the associated flowline. An excavation remains open surrounding the former wellhead. The wellhead has been cut and capped. The base of the excavation sidewalls appeared to have partially eroded. Stockpiled soil utilized as a berm surrounded the open excavation. A small excavation was visible southeast of the former wellhead. Vegetation appears depressed in an area east of the former wellhead. Quarterly reporting is required under Remediation Project # 34664; the last Form 27 for this project was submitted 03/24/2025 (Document Number 404137777) and was denied by ECMC on 04/21/2025. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 — Supplemental Report for closure was due by 08/11/2024.

Corrective Action: **Operator shall submit delinquent form(s) for this project.**

Date: 06/30/2025

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Waste Management:**

Type Management Condition GPS (Lat) (Long)

	Other				
Comment	The well casing and a segment of white plastic pipe were visible adjacent to the wellhead excavation.				
Corrective Action	Remove unnecessary equipment to comply with Rule 606 and dispose of E&P waste in accordance with Rule 905.				Date: 07/01/2025
	Piles				
Comment	Unmarked soil stockpiles were observed on location with no stormwater BMPs; no liners were visible.				
Corrective Action	Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.				Date:

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:                      Date Interim Reclamation Completed:                     

Land Use:                     

Comment:                     

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING                     

Comment                     

Corrective Action                      Date                     

1002b. SOIL REMOVAL AND  
SEGREGATION                     

Comment                     

Corrective Action                      Date                     

1002c. PROTECTION OF SOILS                     

Comment                     

Corrective Action                      Date                     

1002E. SURFACE DISTRURBANCE MINIMIZATION                     

Comment                     

Corrective Action                      Date                     

1003a. Waste and Debris removed?                     

Comment                     

Corrective Action                      Date                     

Unused or unneeded equipment onsite?                     

Comment                     

Corrective Action                      Date                     

Pit, cellars, rat holes and other bores closed?                     

Comment                     

Corrective Action                      Date                     

Guy line anchors marked?                     

Comment                     

Corrective Action                      Date

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 

The base of the excavation sidewalls appeared to have partially eroded.

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404242160	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097022">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097022</a>
717100260	ECMC Photo Log - Lowe 1B SWD Well - 05.30.2025	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097015">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097015</a>