

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

06/18/2025

Document Number:

718600668

## FIELD INSPECTION FORM

 Loc ID 317307 Inspector Name: Dunnam, Anthony On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 ECMC Operator Number: 20275  
 Name of Operator: CORAL PRODUCTION CORP  
 Address: 1600 STOUT ST STE 1500  
 City: DENVER State: CO Zip: 80202
**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone          | Email                      | Comment |
|-----------------|----------------|----------------------------|---------|
| Heibel, Krystal |                | krystal.heibel@state.co.us |         |
| Chonka, Jim     | (303) 623-3573 | jpchonka@netscape.net      |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|---------------------|-------------|
| 237991      | WELL     | PA     | 03/26/2022  | OW         | 121-10494 | LINDA 1             | RI          |
| 317307      | LOCATION | AC     |             |            | -         | LINDA-62S52W 19SESE | RI          |

**General Comment:**

This is a Final Reclamation Inspection for PA Well API#121-10494 and its associated tank battery. Well was plugged and abandoned 03/26/2022.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: Undesirable weed kochia is present throughout the location.

Corrective Action: Comply with Rule 606.c. Control weeds on location.

Date:

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:

#

corrective date

Comment: T-posts and metal pipe remain in the pits. Electrical equipment, pipe, posts and wood debris remain on the wellbore location. See attached photos.

See reclamation section for CA.

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 237991 Type: WELL API Number: 121-10494 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 317307 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation project #22462 is active and open. Continue to comply with 900 series rules and regulations.

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed **Fail** \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured **Fail** \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured **Fail** \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage **Fail** \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

|  |  |             |
|--|--|-------------|
|  | <p>This location does not meet Rule 1004 standards. Location has not been recountoured and multiple pits remain on location. Debris and equipment remain in the pits and at the wellhead. Location is surrounded by cropland. See attached pictures.</p> <p>Remediation project #22462 is active and open. Upon closure of active remediation project location should be reclaimed according to Rule 1004.</p> |             |
| Corrective Action:   | <p><b>Equipment and debris removal should have been conducted within 3 months of plugging.</b></p> <p><b>Comply with the reclamation rules to remove all debris, abandoned gathering line risers, and flowline risers, and equipment (regardless of ownership) within three months of plugging (03/26/2022) the associated facility. All work should have been conducted by 06/26/2022.</b></p>                | Date: _____ |
| <p>Overall Final Reclamation <b>Fail</b>      Well Release on Active Location <input type="checkbox"/>      Multi-Well Location <input type="checkbox"/></p> |  |             |

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: At the time of this inspection, no stormwater erosion issues were observed at location or along the access road.

Corrective Action:       Date: \_\_\_\_\_

**Pits:**       NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404246323    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7101078">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7101078</a> |
| 718600669    | Inspection Photos    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7101075">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7101075</a> |