

# LOWE B 2

## Photo Log

**Inspection Comment:** Fence posts with pieces of plastic tape have been installed at the excavations/trenches and depressions; no fencing was visible.

**Corrective Action Requested:** Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.

**Description of Compliance:** Fencing has been installed.

Photos are of fencing around the entire excavation around the tank battery

