

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/09/2025

Submitted Date:

06/19/2025

Document Number:

701104211

FIELD INSPECTION FORM

Loc ID 335542 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288407	WELL	PR	01/01/2025	GW	045-13227	VALLEY FARMS E5	EG
288408	WELL	PR	01/01/2025	GW	045-13226	VALLEY FARMS E6	EG
288411	WELL	PR	01/22/2010	GW	045-13223	VALLEY FARMS E9	EG
288412	WELL	PR	10/08/2013	GW	045-13222	VALLEY FARMS E10	EG
288413	WELL	PR	01/05/2010	GW	045-13221	VALLEY FARMS E11	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Unused flowline risers are missing OOSLAT tags.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Flow Line				
Comment:	Unused flowline risers are missing OOSLAT tags.			
Corrective Action:	Comply with 1100 Rule Series			Date: 07/04/2025

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 288407 Type: WELL API Number: 045-13227 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 288408 Type: WELL API Number: 045-13226 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 288411 Type: WELL API Number: 045-13223 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 288412 Type: WELL API Number: 045-13222 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 288413 Type: WELL API Number: 045-13221 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404248157	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7102833
701104212	Flowline integrity inspection 701104211 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7102827