

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329909

Inspection Document #: 718800409

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRC #3-1116
Location ID: 329909



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding and straw mulch, but vegetation has not yet established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: UPRC #3-1116
Location ID: 329909



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: UPRC #3-1116
Location ID: 329909



Photo 5. Photo taken of ground cover at the well location. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 6. Photo taken of the reference area, south of the well location, facing East.

Inspection Photos
Location Name: UPRC #3-1116
Location ID: 329909



Photo 7. Photo taken of the access road, facing Southwest away from the location. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding and straw mulch, but vegetation has not established to Rule 1004 standards.



Photo 8. Photo taken of the entrance of the access road, facing North towards the location. Photo illustrates that bare ground remains along this portion of the access road.

Inspection Photos
Location Name: UPRC #3-11I6
Location ID: 329909



Photo 9. Photo taken of the tank battery location, facing North. Photo illustrates that final reclamation activities do not appear to have taken place as bare ground and gravel remain across the location.



Photo 10. Photo taken of the tank battery location, facing South. See comments under Photo 9.



Inspection Photos
Location Name: UPRC #3-11I6
Location ID: 329909



Photo 11. Photo taken of the access road, facing North towards the tank battery location. Photo illustrates stormwater erosion along the western portion of the access road.



Photo 12. Photo taken of the access road adjacent to the tank battery location, facing Southeast. Photo illustrates erosion along the edge of the access road and around the culvert.

