

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2025

Submitted Date:

06/19/2025

Document Number:

707801675

FIELD INSPECTION FORMLoc ID 424341 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424356	WELL	PR	05/19/2020	GW	045-20890	FEDERAL 23A-33-691	PR
424362	WELL	PR	05/20/2020	GW	045-20896	FEDERAL 23C-33-691	PR
424363	WELL	PR	06/15/2018	GW	045-20897	FEDERAL 23B-33-691	PR
424371	WELL	PR	06/25/2018	GW	045-20903	FEDERAL 34C-33-691	PR
424377	WELL	PR	05/20/2020	GW	045-20905	FEDERAL 34D-33-691	PR
424378	WELL	PR	05/19/2020	GW	045-20906	FEDERAL 34B-33-691	PR
449864	WELL	PR	06/25/2018	GW	045-23493	CSF 41C-4-791	PR
449868	WELL	PR	05/20/2020	GW	045-23497	CSF 41B-4-791	PR
449870	WELL	PR	05/20/2020	GW	045-23499	CSF 41D-4-791	PR

General Comment:**CECMC Inspection Report Summary**

On Wednesday 6/18/2025, I, Inspector Scott Ramsey, conducted a follow up inspection/audit at TEP MDP 25, at Location # 424341 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

During this inspection the following compliance issues were observed:

1. Unused equipment (ECD) supply gas is disconnected at tank battery. Main line form tanks is disconnected at ECD.
 2. Chemical containment has fluid in it.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (ECD) supply gas is disconnected at tank battery. Main line form tanks is disconnected at ECD.		
Corrective Action:	Remove stored equipment, put into service or provide proper documentation to keep on location.	Date:	08/01/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 9		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 1	
Comment:	See housekeeping for C/A	
Corrective Action:		Date:
Type: Gas Meter Run	# 9	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 14	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	1 Chemical containment has fluid in it.	
Corrective Action:	Evacuate fluids in containments to provide adequate space in case of a spill	Date: 06/21/2025
Type: Horizontal Heated Separator	# 9	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities				
Facility ID:	424356	Type:	WELL	API Number: 045-20890 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424362	Type:	WELL	API Number: 045-20896 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424363	Type:	WELL	API Number: 045-20897 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424371	Type:	WELL	API Number: 045-20903 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424377	Type:	WELL	API Number: 045-20905 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424378	Type:	WELL	API Number: 045-20906 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	449864	Type:	WELL	API Number: 045-23493 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	449868	Type:	WELL	API Number: 045-23497 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
Gravel						Sparse to none in most areas
		Culverts				
Ditches						
Culverts						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404249445	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7104244
707801681	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7104238