

NININGER 11-1-1645

Photo Log

Inspection Comment: Fence posts and a single metal wire have been installed around one of the open excavations but do not adequately limit access.

Corrective Action Requested: Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.

Description of Compliance: Excavation area secured with fencing per Rule 913.b.(5)

Photos are fencing around the entire Nininger Tank Battery excavation.

