

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 331036

Inspection Document #: 718800419

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DANIELS K-64N66W/5SESW
Location ID: 331036



Photo 1. Photo taken of the tank battery location, facing Northeast. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards and the location is dominated by weedy annual vegetation.



Photo 2. Photo taken of the tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DANIELS K-64N66W/5SESW
Location ID: 331036



Photo 3. Photo taken from the multi-well location, from well API# 123-20058 (DANIELS K #5-14 X), facing North. Photo illustrates that the well location meets Rule 1004 standards.



Photo 4. Photo taken from the well location, from well API# 123-20058 (DANIELS K #5-14 X), facing East. See comments under Photo 3.

Inspection Photos
Location Name: DANIELS K-64N66W/5SESW
Location ID: 331036



Photo 5. Photo taken from the multi-well location, from well API# 123-20058 (DANIELS K #5-14 X), facing South. See comments under Photo 3.



Photo 6. Photo taken from the multi-well location, from well API# 123-20058 (DANIELS K #5-14 X), facing West. See comments under Photo 3.

Inspection Photos
Location Name: DANIELS K-64N66W/5SESW
Location ID: 331036



Photo 7. Photo taken from the multi-well location, from well API# 123-18028 (DANIELS #5-1416), facing South. Photo illustrates that the well location appears to meet Rule 1004 standards and a future inspection will be conducted during the appropriate reproductive stage.



Photo 8. Photo taken from the multi-well location, from well API# 123-18028 (DANIELS #5-1416), facing West. See comments under Photo 7.

Inspection Photos

Location Name: DANIELS K-64N66W/5SESW

Location ID: 331036



Photo 9. Photo taken from the multi-well location, from well API# 123-18028 (DANIELS #5-1416), facing South. See comments under Photo 7.



Photo 10. Photo taken from the multi-well location, from well API# 123-18028 (DANIELS #5-1416), facing West. See comments under Photo 7.



Inspection Photos

Location Name: DANIELS K-64N66W/5SESW

Location ID: 331036



Photo 11. Photo taken of the reference area for well API# 123-18028 (DANIELS #5-1416), east of the well location, facing Southeast.



Photo 12. Photo taken of the reference area, west of the tank battery location, facing North. Photo illustrates perennial grass vegetation.

