

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

06/30/2025

Document Number:

718200049**FIELD INSPECTION FORM**Loc ID 421051 Inspector Name: Metz, Collin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Anderson, Laurel		laurel.anderson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421253	WELL	PA	11/08/2022	OW	123-32869	DECHANT 23-1	EI
489116	SPILL OR RELEASE	AC	01/24/2025		-	Dechant 23-1	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 489116 and Remediation Project #23824. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were operator personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489116

Spill Name: Dechant 23-1

Remediation Project #: 23824

Well API: 05-123-32869

Reported Date of Discovery: 01/23/2025

Date of Inspection: 06/12/2025

Weather Conditions: Sunny/Breezy 85-90 F

Spills are located within or adjacent to:

-Crop land

Current Site Status:

-Backfilled and interim reclamation has started

See attached corrective actions. Form 19 and 27- Supplementals are required.

Inspected Facilities									
Facility ID:	421253	Type:	WELL	API Number:	123-32869	Status:	PA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	489116	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: A historical release was discovered 01/23/2025 during Remediation Project 23824 and the Form 19 Initial with Supplemental Report (Doc # 404069440) was received on 01/24/2025. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure that was due 04/24/2025 and is 63 days late. Operator shall submit and request closure of the Form 19 by checking the box for "Work proceeding under an approved Form 27 (Rule 912.c)" and submit a Supplemental Form 27 for this project within 14 days. Operator is out of compliance with Rule 913.e.(3). Quarterly reporting (90 days) is required under Remediation Project #23824. Operator is past due on quarterly reporting. The last Form 27 was received on 01/21/2025 (Doc # 404060418) and denied by ECMC with comment, "Operator states " Please note that laboratory detection limits for several organic constituents in the attached Eagle Site Investigation Report are listed as 0.020 milligrams per kilogram (mg/kg) and 0.005 mg/kg for WH-FS-01@6 ' whereas the laboratory report lists detection limits of 0.0067 mg/kg" ECMC has denied this form as it is not appropriate to enter errors into the official record. In accordance with Rule 207 Operator shall conduct a full QAQC review and submit a complete and accurate report."

Corrective Action: **Operator shall submit delinquent forms for this project.**

Date: 07/14/2025

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718200050	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7121913