

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2025

Submitted Date:

06/30/2025

Document Number:

713400889**FIELD INSPECTION FORM**Loc ID 323851 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|-------|------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Haverkamp, Curtis | | curtis.haverkamp@state.co.us | |
| ENERGY, VISION | | mollieo@maralexinc.com | |
| Toews, Wesley | | wtoews@blm.gov | |
| Koch, Benjamin | | bzkoch@blm.gov | |
| ENERGY, VISION | | pbechtolt@maralexinc.com | |
| ENERGY, VISION | | mrine20@maralexinc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 210985 | WELL | PR | 03/01/2021 | CBM | 045-06743 | SOUTH SHALE RIDGE 10-7 | PR |

General Comment:

CECMC Inspection/Audit Report Summary

On 06/26/2025 at approximately 13:13 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD at Location ID #323851 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Equipment - Multiple open ended piping on production tank/wildlife hazard/available for entry by wildlife with a CA date of 07/7/2025
2. Equipment - PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 07/7/2025
3. Housekeeping - Weeds/undesirable plant species on location with a CA date of 07/7/2025
4. Housekeeping - Staining on location with a CA date of 07/7/2025
5. Inspected Facilities - Well lacks wellbore diagram/not in compliance with CECMC rules with a CA date of 07/30/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

| Location | | | | |
|--|--|--------|-------|-----------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Access | | | |
| Corrective Action | L | | Date: | |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | OTHER | | | |
| Comment: | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. | | | |
| Corrective Action: | | | Date: | |
| Type | WELLHEAD | | | |
| Comment: | Sign on pump jack skid | | | |
| Corrective Action: | | | Date: | |
| Type | BATTERY | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Emergency Contact Number: | | | | |
| Comment: | 970-858-8550/911 | | | |
| Corrective Action: | | | Date: | |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard | | | |
| Corrective Action: | Oil and Gas Locations will be kept free of all Undesirable Plant Species | | Date: | 07/07/2025 |
| Type | OTHER | | | |
| Comment: | Staining on location | | | |
| Corrective Action: | Remove and properly dispose of all stained materials. | | Date: | 07/07/2025 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Equipment: | | | | corrective date |
| Type: Pump Jack | # 1 | | | |

| | | | |
|-----------------------------------|---|-------|------------|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | No form of pressure monitoring equipment. Bradenhead valve is accessible | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | PRV vent line does not comply with CECMC pressure safety device rules | | |
| Corrective Action: | Comply with CECMC wildlife rules | Date: | 07/07/2025 |
| Type: Deadman # & Marked | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 3 | | |
| Comment: | Multiple open ended piping on production tank/wildlife hazard/available for entry by wildlife | | |
| Corrective Action: | Comply with CECMC wildlife rules | Date: | 07/07/2025 |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Summit Midstream | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------------------|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | Tank not equipped with telemetry | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|------------|--|
| Condition | Inadequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|------------|
| Facility ID: | 210985 | Type: | WELL | API Number: | 045-06743 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| | Well lacks wellbore diagram/not in compliance with CECMC rules | | | | | | | | |
| Corrective Action: | Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17 | | | | | | | Date: | 07/30/2025 |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Check Dams | | | | |
| | | Compaction | | | | |
| | | Culverts | | | | |
| Berms | | | | | | |
| Gravel | | | | | | Sparse |
| Compaction | | | | | | |
| | | Gravel | | | | Sparse |
| | | Ditches | | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| Please refer to Equipment, Housekeeping & Inspected Facilities for corrective actions. | popejoyd | 06/30/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------------|---|
| 713400890 | 713400889 Inspection-Audit Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7122371 |